

# Oil Field Environmental Incident Summary

**Incident:** 20150119100121      **Date/Time of Notice:** 01/19/2015 10:01

**Responsible Party:** QEP ENERGY COMPANY

**Well Operator:** QEP ENERGY COMPANY

**Well Name:** MHA 1-06-07H-147-92

**Field Name:** HEART BUTTE

**Well File #:** 24846

**Date Incident:** 1/18/2015      **Time Incident:** 08:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 148

**Rng:** 92

**Sec:** 31

**Qtr:** NW SW

**Location Description:** BIA 12 to BIA 14 to BIA Loop 17, SE to well pad location

**Submitted By:** Jerry Reinisch

**Received By:**

**Contact Person:** Jerry Reinisch  
1050 17TH ST STE 500  
DENVER, CO 80265

**General Land Use:** Pasture

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 3 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Barrels	1	Barrels		
<b>Brine</b>	1	Barrels	1	Barrels		

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

low risk as unit was shut in immediately (LOTO), crude oil/produced water is potentially flammable.

**Areal Extent:**

Light mist was blown by 30-50 mph northwest winds outside the metal containment coating the snow.

**Potential Environmental Impacts:**

spill confined to location and the areas were remediated immediately.

**Action Taken or Planned:**

treater design and gasket functionality being reviewed by engineering staff. Unit will remain shut-in until decision made on how to best repair the unit.

**Wastes Disposal Location:** Contaminated materials transported to Clean Energy disposal via manifest. Fluids recovered placed back into system.

**Agencies Involved:**

**Updates**

---

**Date:** 1/20/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.