

# Oil Field Environmental Incident Summary

**Incident:** 20150206102537      **Date/Time of Notice:** 02/06/2015 10:25

**Responsible Party:** NEWFIELD PRODUCTION COMPANY

**Well Operator:** NEWFIELD PRODUCTION COMPANY

**Well Name:** SERGEANT MAJOR 1-21H

**Field Name:** SOUTH TOBACCO GARDEN

**Well File #:** 18086

**Date Incident:** 2/5/2015      **Time Incident:** 11:45

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 99

**Sec:** 21

**Qtr:** NE NW

**Location Description:**

**Submitted By:** Tim Eaton

**Received By:**

**Contact Person:** Tim Eaton  
363 N. SAM HOUSTON, PKWY E  
SUITE 100  
HOUSTON, TX 77060

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	4	Barrels	4	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 4/24/2015

**Clean Up Concluded:** 4/10/2015

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

Snow and some vegetation in reclaimed area was misted with oil.

**Action Taken or Planned:**

Free liquids were removed from the flare pit and the snow was gathered up in a pile on location. A thaw is expected next week at which time we will recover remaining liquids and solids gathered up and dispose of them.

**Wastes Disposal Location:** Liquids will be put back in the tanks on location and solids will be disposed of properly.

**Agencies Involved:**

**Updates**

---

**Date:** 2/6/2015    **Status:** Reviewed - Follow-up Required

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to treater leak, sprayed on reclaimed area according to the report. Followup is necessary.

---

**Date:** 2/11/2015    **Status:** Inspection

**Author:** Cooper, Mike

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site, wind NW 10-15 mph, 15°F.  
Spray was apparent. Pictures were taken as evidence of work in progress.  
Material that has been excavated has been left on site and has not been disposed of.  
Further followup is necessary to check for disposal and vegetative growth in the future.

---

**Date:** 5/14/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 13:15 p.m. The weather was cloudy, 48°F, with the wind from the northeast 5-10 mph. The stacked soil has been removed. The spray occurred on the west sidehill of pad. Straw wattles have been placed in the cleaned-up area. This is still part of the pad, so NDIC Oil & Gas retains oversight. No further followup needed. 47.79115; - 103.35311