

# Oil Field Environmental Incident Summary

**Incident:** 20150209150859      **Date/Time of Notice:** 02/09/2015 15:08

**Responsible Party:** Texakota, Inc.

**Well Operator:** TEXAKOTA, INC.

**Well Name:** M. BORSTAD 10-1

**Field Name:** WEST TIOGA

**Well File #:** 7401

**Date Incident:** 2/5/2015      **Time Incident:** 14:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 157

**Rng:** 95

**Sec:** 10

**Qtr:** NE NW

**Location Description:** Well Battery Heater Treater leaked 3-4 GALLONS of oil and 80 bbls of salt Water

**Submitted By:** Bradford Schmalfuss

**Received By:**

**Contact Person:** Bradford Schmalfuss  
2707 KIPLING  
HOUSTON, TX 77098

**General Land Use:** Pasture

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	4	Gallons	4	Gallons	4	gallons
<b>Brine</b>	80	Barrels	75	Barrels	80	barrels
<b>Other</b>			5	Barrels		

**Description of Other Released Contaminant:**

None

**Inspected:**

**Written Report Received:** 1/23/2017

**Clean Up Concluded:** 2/26/2015

**Risk Evaluation:**

Minimal

**Areal Extent:**

40 feet X 40 Feet right around Heater Treater inside Facility area

**Potential Environmental Impacts:**

Some released water froze and will have to be scraped and cleaned in next few days

**Action Taken or Planned:**

Immediately cleaned up 95% of spill

**Wastes Disposal Location:** Certified disposal facility

**Agencies Involved:**

**Updates**

---

**Date:** 2/9/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

---

**Date:** 2/24/2015    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 3:30 2/24/2015.

Spill was being scraped up at the time of inspection. Impacted material was being placed on the wellpad.

More followup is necessary with the company to ensure proper cleanup.

---

**Date:** 4/1/2015    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Sample results received showing additional impact in area that wasn't cleaned up at the time of the initial inspection.

Formal letter sent to responsible party requesting further sampling to delineate the extent of the impact and remove the impacted soil.

More followup is necessary.