

# Oil Field Environmental Incident Summary

**Incident:** 20150220114913      **Date/Time of Notice:** 02/20/2015 11:49

**Responsible Party:** Triangle USA Petroleum Corporation

**Well Operator:** TRIANGLE USA PETROLEUM CORPORATION

**Well Name:** DWYER 149-101-2-11-1H

**Field Name:** ANTELOPE CREEK

**Well File #:** 23464

**Date Incident:** 2/19/2015      **Time Incident:** 22:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 149

**Rng:** 101

**Sec:** 2

**Qtr:** LO T2

**Location Description:** Mostly on well/facility site however some crude spray did mist onto neighboring land.

**Submitted By:** Brittany Vannoy

**Received By:**

**Contact Person:** Brittany Vannoy  
1200 17TH ST., SUITE 2600  
DENVER, CO 80202-5826

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.5	Barrels			0	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 3/7/2016

**Clean Up Concluded:** 6/3/2015

**Risk Evaluation:**

None.

**Areal Extent:**

**Potential Environmental Impacts:**

None.

**Action Taken or Planned:**

The well shut itself in, the spill will be cleaned and remediated on-site. Landowner will determine how he wants TUSA to attend to crude mist off-location.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 2/23/2015    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to unspecified cause, sprayed off location according to the report. Followup is necessary.

---

**Date:** 2/25/2015    **Status:** Inspection

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Approximately 0.5 bbl were released and were wind blown about 15 feet off the well pad. Triangle is still in negotiations with the landowner on access and site disposition. Off-site impacts appear to be limited to a light spray on snow and vegetation. Triangle Petroleum was asked to provide documentation of the landowner's wishes.

---

**Date:** 6/3/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 16:59 p.m. The weather was clear, 66°F, with the wind from the north east 5-10 mph. I could not see any issues in the fields to the north or south of the pad. The fields have been seeded, and the crops are growing. No further followup is needed at this time.

---

**Date:** 11/5/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Requested any documentation the company has about the site.

---

**Date:** 2/23/2016    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Requested documentation about the site.

---

**Date:** 3/3/2016    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received follow-up spill report.

---

**Date:** 3/7/2016    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received follow-up spill report.