

Oil Field Environmental Incident Summary

Incident: 20150220143230 **Date/Time of Notice:** 02/20/2015 14:32

Responsible Party: MCRAE & HENRY, LTD.

Well Operator: MCRAE & HENRY, LTD.

Well Name: HANSEN STATE 23-16

Field Name: LAKE ILO

Well File #: 10783

Date Incident: 2/20/2015 **Time Incident:** 07:00

Facility ID Number:

County: DUNN

Twp: 145

Rng: 93

Sec: 16

Qtr:

Location Description: The spill was contained within the tank battery berm

Submitted By: Nathan Ehlis

Received By:

Contact Person: Nathan Ehlis
1600 STOUT ST, Suite 580
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels

Brine

Other

Description of Other Released Contaminant:

The spill was a water oil mix that came from the overflow of a production water tank.

Inspected:

Written Report Received: 3/25/2015

Clean Up Concluded: 3/11/2015

Risk Evaluation:

There is no risk, all spilled materials were contained within the tank berm.

Areal Extent:

The spill was contained within the tank berm.

Potential Environmental Impacts:

There is no risk to the environment, the spill was contained within the berm. All liquid will be sucked back up and all contaminated soil will be disposed of properly.

Action Taken or Planned:

Better communication between both companies to make sure that this does not occur in the future.

Wastes Disposal Location: All solids and liquids will be taken to the Knudtson SWD.

Agencies Involved:

Updates

Date: 2/23/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.