

# Oil Field Environmental Incident Summary

**Incident:** 20150228120540      **Date/Time of Notice:** 02/28/2015 12:05

**Responsible Party:** Petro Harvester Operating Company, LLC

**Well Operator:** ENDURO OPERATING, LLC

**Well Name:** EARL 1

**Field Name:** PORTAL

**Well File #:** 10902

**Date Incident:** 2/27/2015      **Time Incident:** 14:30

**Facility ID Number:**

**County:** BURKE

**Twp:** 164

**Rng:** 91

**Sec:** 31

**Qtr:**

**Location Description:**

**Submitted By:** Gary Watson

**Received By:**

**Contact Person:** Galen Kalmbach  
103 First Avenue NE  
Mohall, ND 58761

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.8 Mile

**Distance Nearest Water Well:** 0.8 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	5	Barrels	5	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/12/2015

**Clean Up Concluded:** 4/30/2015

**Risk Evaluation:**

Minimal effect on cultivated land.

**Areal Extent:**

5 bbl of oil pool outside of dike - 20' x 20'. A fine oil mist deposited on the snow - 30' x 75'.

**Potential Environmental Impacts:**

Minimal effect on cultivated land.

**Action Taken or Planned:**

Jim Potts - NDIC inspector was notified. The landowner and tenant farmer will be identified and notified as soon as possible. The affected snow cover and soil will be scraped-up, collected and delivered to an approved disposal facility.

**Wastes Disposal Location:** Approved disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 3/2/2015    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the contaminant sprayed off location due to an on-location valve/piping leak. Follow-up is necessary.

---

**Date:** 4/22/2015    **Status:** Awaiting Documentation

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

4/22/2015 at 16:01, on location. Rolloff on site with visibly impacted soil. Area south of tank battery and treater has been scraped. Talked with report contact and requested sample be taken from scraped area to confirm cleanup.

---

**Date:** 6/17/2015    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received sample results. TPH results below detection limits. No further follow-up required.