

Oil Field Environmental Incident Summary

Incident: 20150305161011 **Date/Time of Notice:** 03/05/2015 16:10

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: FRYBURG HEATH-MADISON UNIT K-806HR

Field Name: FRYBURG

Well File #: 13207

Date Incident: 3/5/2015 **Time Incident:** 07:30

Facility ID Number:

County: BILLINGS

Twp: 139 **Rng:** 100 **Sec:** 18 **Qtr:**

Location Description: Released fluid is currently contained within secondary containment on location.

Submitted By: Troy Brunsell

Received By:

Contact Person: Jason Henry
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	50	Barrels	40	Barrels	40	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/13/2016

Clean Up Concluded: 4/13/2015

Risk Evaluation:

Produced fluid contained inside secondary containment.

Areal Extent:

Potential Environmental Impacts:

Potential ground water impact, facility soil.

Action Taken or Planned:

Vac truck dispatched to location, recovered an estimated 40 bbls. of produced fluid. A spill cleanup crew will be dispatched to cleanup the impacted area.

Wastes Disposal Location: Approved waste facility

Agencies Involved:

Updates

Date: 3/5/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.