

# Oil Field Environmental Incident Summary

**Incident:** 20150312164002      **Date/Time of Notice:** 03/12/2015 16:40

**Responsible Party:** ENERPLUS RESOURCES USA CORPORATION

**Well Operator:** ENERPLUS RESOURCES USA CORPORATION

**Well Name:** HENRY BAD GUN 16B-21-1H

**Field Name:** MOCCASIN CREEK

**Well File #:** 18790

**Date Incident:** 3/12/2015      **Time Incident:** 08:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 147

**Rng:** 93

**Sec:** 16

**Qtr:**

**Location Description:** Well site

**Submitted By:** Tony Lucero

**Received By:**

**Contact Person:** Josh Ruffo  
US BANK TOWER  
950 17TH ST STE 2200  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	5	Barrels	5	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

NA

**Inspected:**

**Written Report Received:** 7/25/2016

**Clean Up Concluded:** 3/12/2015

**Risk Evaluation:**

None

**Areal Extent:**

Entire release was contained on well site.

**Potential Environmental Impacts:**

Release only impacted well site surface, which was excavated and shipped offsite for disposal.

**Action Taken or Planned:**

Oil was re-diverted to oil tank. Free liquids were vacuumed up and contaminated soil was collected and shipped to an approved offsite disposal facility. The importance of following applicable tank filling procedures was communicated to affected personnel to prevent a recurrence.

**Wastes Disposal Location:** At an approved offsite disposal facility.

**Agencies Involved:** Bureau of Indian Affairs, Bureau of Land Management, and Three Affiliated Tribes

**Updates**

---

**Date:** 3/13/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.