

Oil Field Environmental Incident Summary

Incident: 20150326141154 **Date/Time of Notice:** 03/26/2015 14:11

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: A. N. NELSON (NCT-1) 3

Field Name: BLUE BUTTES

Well File #: 11094

Date Incident: 3/24/2015 **Time Incident:** 14:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 95

Sec: 5

Qtr:

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.3 Mile

Distance Nearest Water Well: 0.3 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.7	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/25/2015

Clean Up Concluded: 3/30/2015

Risk Evaluation:

The source of the release was secured immediately upon discovery of the incident. A vac truck was used to recover as much of the oil as practicable.

Areal Extent:

Approximately 50 feet x 50 feet, off the east side of the location.

Potential Environmental Impacts:

The release occurred above ground, and a vacuum truck was dispatched to the location in order to recover as much of the released crude oil as practicable. The impacted soil on the location and off of the location to the east will be excavated and transported off-site for proper disposal.

Action Taken or Planned:

The impacted soil on the location and off of the location to the east will be excavated and transported off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 3/27/2015 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 3/27/15, at 9:30 a.m. Spray from stuffing box went off site to the east of well pad. There was visible impact to fence line as well as stubble field to the east. Impact off site was approximately 75 X 100 ft. More followup is required.

Date: 3/27/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 3/30/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 15:55 p.m. The weather is clear, 68°F, with the wind from the northwest at 10-15 mph. The consultant and cleanup crew were at the site trying to locate the lines on pad. The standing oil has been sucked up. They have not started on the sprayed area in field. The area sprayed is east of well pad. The plan is to start cleaning up field later this week. Clearance samples and map of spill will be submitted to the NDDoH. More followup required. 47.92877; -102.86752

Date: 4/8/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 11:36 a.m. The weather was cloudy and 35°F, with the wind from the southeast at 10-20 mph. The area in the field sprayed has been scraped up, and soil has been hauled away. Samples were taken. No further followup needed.

Date: 10/13/2015 **Status:** No Further Action Requested

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Last inspector reviewed documentation and wrote a No Further Action letter for the responsible party dated 10/9/15. No further follow-up needed at this time.