

Oil Field Environmental Incident Summary

Incident: 20150401100222 **Date/Time of Notice:** 04/01/2015 10:02

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: ERICKSON CTB

Field Name: CEDAR HILLS

Well File #:

Date Incident: 3/31/2015 **Time Incident:** 16:30 **Facility ID Number:** 413695-19

County: BOWMAN **Twp:** 131 **Rng:** 105 **Sec:** 27 **Qtr:** NE NE

Location Description: approx. 100 feet south of the edge of Erickson CTB

Submitted By: Josh Cuppy

Received By:

Contact Person: Josh Cuppy
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels		
Brine	3	Barrels	3	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Released fluids were contained within open excavation ditch.

Potential Environmental Impacts:

None

Action Taken or Planned:

Associated well was shut in. Recovered standing fluids and impacted soil.

Wastes Disposal Location: Fluids were recovered back into system while impacted soil will be sent to approved landfill.

Agencies Involved: BLM

Updates

Date: 4/1/2015 **Status:** Reviewed - Follow-up Required **Author:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of oil and brine, south of the central tank battery, was contained within an open excavation ditch according to report. No cause of incident included, and report states that it was contained within dike area. However, pasture is included as the general land use, and location description is approximately 100 feet south of the edge of Erickson CTB. Further followup is necessary.

Date: 4/7/2015 **Status:** Inspection **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 11:19 a.m. The weather was cloudy, 45°F, with the wind from the west at 10-15 mph. The new pipeline excavation is located south of the tank battery. The break has been repaired, and the trench has been filled in. No further followup needed. 46.14639, -103.78868