

# Oil Field Environmental Incident Summary

**Incident:** 20150402103649      **Date/Time of Notice:** 04/02/2015 10:36

**Responsible Party:** Taqa North USA

**Well Operator:** TAQA NORTH USA, INC.

**Well Name:** SKEDSVOLD 1

**Field Name:** ALEXANDER

**Well File #:** 8165

**Date Incident:** 3/28/2015      **Time Incident:** 12:11

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151

**Rng:** 101

**Sec:** 23

**Qtr:** SE NE

**Location Description:**

**Submitted By:** Casey Elm

**Received By:**

**Contact Person:** Casey Elm  
7400 E Caley Ave Ste 200  
WAS:PRIMEWEST PETROLEUM, INC  
Centennial, CO 80111

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained in Dike:** No

**Reported to NRC:** No

**Spilled Units**

**Recovered Units**

**Followup Units**

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Smoke from grass burning

**Areal Extent:**

**Potential Environmental Impacts:**

Should not be any

**Action Taken or Planned:**

Raised flares so weeds blowing through will not ignite

**Wastes Disposal Location:** There was no waste

**Agencies Involved:** Local Fire Department

**Updates**

---

**Date:** 4/2/2015    **Status:** Reviewed - No Action Required

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, release was not contained and grass near the pad was ignited and burned. Spoke with the company representative via phone on 4/2/15 and received information that there was no release and their assessment of the situation was that something blew through the flare on the pad and ignited the grass surrounding the pad. The fire department was on site and put out the fire. The landowner had been contacted; no issues were raised to company contact. No further followup needed at this time.