

Oil Field Environmental Incident Summary

Incident: 20150428185844 **Date/Time of Notice:** 04/28/2015 18:58

Responsible Party: MARATHON OIL COMPANY

Well Operator: MARATHON OIL COMPANY

Well Name: ROEHR USA 34-7H

Field Name: WOLF BAY

Well File #: 24798

Date Incident: 4/26/2015 **Time Incident:** 09:00

Facility ID Number:

County: DUNN

Twp: 146

Rng: 92

Sec: 18

Qtr:

Location Description: The Roehr wellhead had a stuffing box leak. A total of 84.90 gallons of oil leaked. This location has a poly tub on the site designed to catch the fluid from a stuffing box leak. The poly tub, or secondary containment, caught the entire spill except for a mist which totaled 0.12 gallons. The misted 0.12 gallons all remained on location.

Submitted By: Duell Petsch

Received By:

Contact Person: Duell Petsch

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	84.9	Gallons	84.9	Gallons		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk as entire spill was contained on the well site. All but 0.12 gallons were contained in secondary containment.

Areal Extent:

Potential Environmental Impacts:

Impacts are minimal as spill is entirely cleaned up, no spilled fluid left location, and 84.7 of the 84.9 gallons were contained within the poly tub (secondary containment).

Action Taken or Planned:

Well was shut in upon finding the spill. Spill was cleaned up immediately. The stuffing box rubbers were changed out.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 4/29/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to stuffing box leak, remained on location within the diking according to the report. NDIC retains oversight.