

Oil Field Environmental Incident Summary

Incident: 20150429194632 **Date/Time of Notice:** 04/29/2015 19:46

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: BERGER 156-100-7-6-1H

Field Name: EAST FORK

Well File #: 21198

Date Incident: 4/29/2015 **Time Incident:** 05:00

Facility ID Number:

County: WILLIAMS

Twp: 156 **Rng:** 100 **Sec:** 18 **Qtr:**

Location Description: Between the Berger/Jackman 156-100 and Jackman 2-18 well pads. Area covers about 25 ft wide and 550 ft long

Submitted By: Sadie Fliegel

Received By:

Contact Person: Sadie Fliegel
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Badlands Terrain

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	40	Barrels			40	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 5/15/2015

Clean Up Concluded: 5/8/2015

Risk Evaluation:

None Noted

Areal Extent:

Between the Berger/Jackman156-100 and Jackman2-18 well pads. Area = about 25 ft wide and 550 ft long

Potential Environmental Impacts:

None Noted

Action Taken or Planned:

The saltwater line was isolated from the main pipeline (Otter Creek). The removal of saltwater by hydrovac is still in process. The impacted soil will be dug up and replaced with new soil.

Wastes Disposal Location: Impacted soil and liquids will be taken to an appropriate disposal.

Agencies Involved:

Updates

Date: 4/30/2015 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, was not contained on location according to the report. Followup is necessary.

Date: 5/27/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12:30 5/27/2015.

Spill cleaned up at the time of inspection. Samples are needed to confirm cleanup status.

More followup is necessary to ensure proper cleanup.

Date: 6/1/2015 **Status:** Awaiting Documentation

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Email sent to company contact requesting confirmation cleanup samples.

More followup is necessary.

Date: 10/8/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 10/8/2015.

No sign of impacts at the location, but a request has been sent to the company to reseed area.

No follow-up is necessary.