

Oil Field Environmental Incident Summary

Incident: 20150511160119 **Date/Time of Notice:** 05/11/2015 16:01

Responsible Party: SECURE ENERGY SERVICES USA, LLC

Well Operator: SECURE ENERGY SERVICES USA, LLC

Well Name: 13 MILE SWD 1

Field Name: TYRONE

Well File #: 90159

Date Incident: 5/10/2015 **Time Incident:** 02:30

Facility ID Number:

County: WILLIAMS

Twp: 156 **Rng:** 101 **Sec:** 12 **Qtr:**

Location Description: Facility topsoil near west garage door of operations building, >200 sq ft

Submitted By: John Albert

Received By:

Contact Person: Josh Mosbrucker
555 17TH ST STE 800
DENVER, CO 80202-3908

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 3000 Feet

Distance Nearest Water Well: 750 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Gallons	25	Gallons		
Brine	20	Gallons	20	Gallons		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

minimal, liquids vacced up within hours, contaminated soils removed to solids pad

Areal Extent:

Potential Environmental Impacts:

negligible, spill is contained on site pad and limited to a small area (<200 sq ft)

Action Taken or Planned:

Spill happened in a low lying area and was limited in size. Liquids were vacced up and offloaded, affected topsoil was removed and disposed of on solids pad for processing. Drain valves will be replaced to reduce likelihood of repeat incident.

Wastes Disposal Location: disposed of on solids pad, evaluated and processed on site

Agencies Involved:

Updates

Date: 5/11/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.