

Oil Field Environmental Incident Summary

Incident: 20150513222948 **Date/Time of Notice:** 05/13/2015 22:29

Responsible Party: ONEOK Rockies Midstream

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Cherry Creek Compressor Station

Field Name:

Well File #:

Date Incident: 5/13/2015 **Time Incident:** 09:00

Facility ID Number:

County: MCKENZIE

Twp: 149

Rng: 100

Sec: 18

Qtr: SW

Location Description: Cherry Creek Compressor Station
2114134th Avenue NW Arnegard ND 58835

Submitted By: Kim Rudningen

Received By:

Contact Person: Kimberly Rudningen
2700 Lincoln Ave SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units
--	---------	-------	-----------	-------

	Followup	Units
--	----------	-------

Oil

Brine

Other 0.5 Gallons

Description of Other Released Contaminant:

natural gas condensate

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no immediate risks associated with this release

Areal Extent:

The impact was minimal and was contained to the facility soil.

Potential Environmental Impacts:

There are no adverse environmental impacts as a result of this release.

Action Taken or Planned:

The valve was immediately closed upon discovery. The impacted soil was immediately cleaned up and containerized.

Wastes Disposal Location: The wastes will be disposed of in a certified landfill.

Agencies Involved:

Updates

Date: 5/14/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to a valve/piping connection leak at compressor station. Followup is required.

Date: 5/20/2015 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phoned company contact to determine whether an on-site inspection was warranted due to low volume (.5 gallons) of released product. Company contact declared to me that the release was very small in size and was immediately contained and removed at the time of incident. No further followup needed at this time.