

# Oil Field Environmental Incident Summary

**Incident:** 20150519094752      **Date/Time of Notice:** 05/19/2015 09:47

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** CAPA-MADISON UNIT L-213HR

**Field Name:** CAPA

**Well File #:** 1017

**Date Incident:** 5/18/2015

**Time Incident:** 10:02

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 95

**Sec:** 19

**Qtr:**

## Location Description:

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Jason Henry  
3015 16th Street SW, Suite 20  
Minot, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1.5 Mile

**Distance Nearest Water Well:** 1.5 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	10	Barrels	5	Barrels		

## Description of Other Released Contaminant:

Emulsion from well

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

## Risk Evaluation:

There are no immediate risks to report at this time.

## Areal Extent:

**Potential Environmental Impacts:**

The release impacted an estimated 15,550 Sq. Ft. area of Well/Facility soil on site.

**Action Taken or Planned:**

A vac truck was dispatched to the site and was able to recover 5 bbl of standing fluid. Any remaining impacted material will be cleaned up and disposed of.

**Wastes Disposal Location:** The waste will be taken to an approved waste disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 5/20/2015    **Status:** Reviewed - Assigned to Other Agency    **Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.