

# Oil Field Environmental Incident Summary

**Incident:** 20150528075658      **Date/Time of Notice:** 05/28/2015 07:56

**Responsible Party:** ARSENAL ENERGY USA INC.

**Well Operator:** ARSENAL ENERGY USA INC.

**Well Name:** MERLIN R. JOHNSON 1

**Field Name:** LINDAHL

**Well File #:** 8926

**Date Incident:** 5/27/2015      **Time Incident:** 10:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 158

**Rng:** 95

**Sec:** 3

**Qtr:** NE NE

**Location Description:**

**Submitted By:** Gary Ramsdell

**Received By:**

**Contact Person:** Gary Ramsdell  
STE. 1900, 639 5TH AVE. SW  
CALGARY, AB T2P 0M9

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2600 Feet

**Distance Nearest Water Well:** 2600 Feet

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	2	Barrels	2	Barrels	2	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 6/1/2015

**Clean Up Concluded:** 5/27/2015

**Risk Evaluation:**

Little to none

**Areal Extent:**

**Potential Environmental Impacts:**

Little to none

**Action Taken or Planned:**

Valve was adjusted and shut, Valve was capped. @ bbl of saltwater was recovered.

**Wastes Disposal Location:** Recovered saltwater was put back into tank.

**Agencies Involved:**

**Updates**

---

**Date:** 5/28/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.