

Oil Field Environmental Incident Summary

Incident: 20150605095146 **Date/Time of Notice:** 06/05/2015 09:51

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: ERICKSON 12X-35

Field Name: CAPA

Well File #: 19117

Date Incident: 6/4/2015 **Time Incident:** 15:00

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 95 **Sec:** 35 **Qtr:**

Location Description:

Submitted By: Kaylan Dirx

Received By:

Contact Person: Kaylan Dirx
P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Barrels	20	Barrels	20	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/5/2016

Clean Up Concluded: 7/2/2015

Risk Evaluation:

None- majority of liquids were contained within the lined metal treater berm. Free fluids were collected and returned to production tanks.

Areal Extent:

Potential Environmental Impacts:

None- majority of liquids were contained within the lined metal treater berm. Free fluids were collected and returned to production tanks.

Action Taken or Planned:

Free fluids were collected and returned to production tanks. Any impacted material will be removed and disposed at an approved facility. Firetube gasket will be replaced.

Wastes Disposal Location: Fluids were returned to the production tanks. Impacted material will be disposed at R360

Agencies Involved:

Updates

Date: 6/5/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, remained on location according to the report. NDIC retains oversight.