

Oil Field Environmental Incident Summary

Incident: 20150614094542 **Date/Time of Notice:** 06/14/2015 09:45

Responsible Party: Pumpco Inc.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: SORENSON 6-16H2

Field Name: ALKALI CREEK

Well File #: 29669

Date Incident: 6/13/2015 **Time Incident:** 13:30

Facility ID Number:

County: MOUNTRAIL

Twp: 154

Rng: 94

Sec: 21

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Chuck Harris
117 Elm Grove Rd.
Valley Veiw , TX 76272

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	2	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

10 ft. by 20 ft. area

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Standing fluid was sucked up and contaminated material was removed, replacing with clean fill.

Wastes Disposal Location: TBD

Agencies Involved: Called Scott Ladner @ 9:44 am on 6/14/2015

Updates

Date: 6/15/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location within the diking, according to the report. NDIC retains oversight.