

# Oil Field Environmental Incident Summary

**Incident:** 20150630163952      **Date/Time of Notice:** 06/30/2015 16:39

**Responsible Party:** XTO ENERGY INC.

**Well Operator:** XTO ENERGY INC.

**Well Name:** TRUCHAN 11X-33H

**Field Name:** MURPHY CREEK

**Well File #:** 16678

**Date Incident:** 6/30/2015      **Time Incident:** 08:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 145

**Rng:** 95

**Sec:** 33

**Qtr:**

**Location Description:**

**Submitted By:** JORDAN WOLF

**Received By:**

**Contact Person:** KAYLAN DIRKX  
P.O Box 1589  
2320 SOUTH CENTRAL AVE.  
SIDNEY, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels	2	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None- spill contained on well pad.

**Areal Extent:**

Release contained on well pad.

**Potential Environmental Impacts:**

None- spill contained on well pad.

**Action Taken or Planned:**

The back pressure regulator was replaced. Any impacted facility soils will be collected and disposed of at an approved waste disposal facility.

**Wastes Disposal Location:** 13 Mile Disposal

**Agencies Involved:**

**Updates**

---

**Date:** 6/30/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a stuffing box leak, remained on constructed well site, according to report. NDIC retains oversight.