

# Oil Field Environmental Incident Summary

**Incident:** 20150711105905      **Date/Time of Notice:** 07/11/2015 10:59

**Responsible Party:** Jettison, Inc. - Ron Evitt

**Well Operator:** JETTISON, INC.

**Well Name:** SUNFLOT HEIRS 1

**Field Name:** STONEVIEW

**Well File #:** 5919

**Date Incident:** 7/10/2015      **Time Incident:** 13:00

**Facility ID Number:**

**County:** BURKE

**Twp:** 161

**Rng:** 94

**Sec:** 30

**Qtr:** SE SW

**Location Description:** The Saltwater Tank over spilled by 2.5 bbls of oil, With water used to recovered the total volume was 3 bbls.

**Submitted By:** Ron Evitt

**Received By:**

**Contact Person:** Ron Evitt

P.O. Box 562

Williston, ND 58802

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.3 Mile

**Distance Nearest Water Well:** 0.3 Mile

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Barrels	2.5	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

We used approximately .5 bbls of FW to help clean up.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none

**Areal Extent:**

All contained, all cleaned up.

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

We cleaned up the mess as fast as we could on 7-10-2015. There is about 2 gallons of oil in the FW house that we will pick up with oil sorbent pads.

**Wastes Disposal Location:** At our nearby Zimmerman SWD well, but the oil will be returned to the Sunflot well.

**Agencies Involved:** The North Dakota Industrial Commission was notified.

**Updates**

---

**Date:** 7/13/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.