

Oil Field Environmental Incident Summary

Incident: 20150727175807 **Date/Time of Notice:** 07/27/2015 17:58
Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Name: OCONNOR 21-2
Field Name: GLASS BLUFF **Well File #:** 10661
Date Incident: 7/27/2015 **Time Incident:** 04:30 **Facility ID Number:**
County: MCKENZIE **Twp:** 151 **Rng:** 103 **Sec:** 2 **Qtr:**
Location Description: Spill contained inside tank berm.

Submitted By: Tappan Souther **Received By:**
Contact Person: Tappan Souther
1200 17TH STREET, SUITE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	4	Barrels		

Brine

Other

Description of Other Released Contaminant:

NA

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Spill 100% contained within tank berm.

Potential Environmental Impacts:

None.

Action Taken or Planned:

Clean up began first thing this morning. 4 BBLS were estimated to be recovered. Tank will be replaced.

Wastes Disposal Location: Johnson 21-3 SWD tanks.

Agencies Involved: None

Updates

Date: 7/28/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on and E&P well pad. NDIC, Oil and Gas Division retain oversight.