

Oil Field Environmental Incident Summary

Incident: 20150806162012 **Date/Time of Notice:** 08/06/2015 16:20

Responsible Party: STATOIL OIL & GAS LP

Well Operator: STATOIL OIL & GAS LP

Well Name: RUTH 28-33 #3H

Field Name: EAST FORK

Well File #: 30431

Date Incident: 8/5/2015 **Time Incident:** 19:30

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 100

Sec: 21

Qtr:

Location Description: All fluids were contained on the well location

Submitted By: Jeremy Mohl

Received By:

Contact Person: Jeremy Mohl
6300 BRIDGE POINT PKY, BLDG 2
SUITE 500
AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5	Barrels	5	Barrels		

Description of Other Released Contaminant:

Mineral based invert drilling mud

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk existed

Areal Extent:

All fluids contained on location

Potential Environmental Impacts:

No potential impacts to the environment do to the construction of the location.

Action Taken or Planned:

All fluids have been vacced up off the location. Once the drilling rig moves off, planned remediation will commence.

Wastes Disposal Location: Waste will be reintroduced into the mud system. Any contaminated location soil will be sent to PDI.

Agencies Involved:

Updates

Date: 8/6/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.