

Oil Field Environmental Incident Summary

Incident: 20150806184246 **Date/Time of Notice:** 08/06/2015 18:42

Responsible Party: Buckhorn Energy Services

Well Operator: BUCKHORN ENERGY SERVICES, LLC

Well Name: Leiseth SWD #1

Field Name: TOBACCO GARDEN

Well File #: 90288

Date Incident: 8/5/2015 **Time Incident:** 22:20

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 99

Sec: 27

Qtr:

Location Description:

Submitted By: Nancy Roberts

Received By:

Contact Person: Nancy Roberts
5613 DTC Parkway Suite 800
Greenwood Village, CO 80111

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	7	Barrels	7	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None all spill was contained.

Areal Extent:

Potential Environmental Impacts:

None all spill was contained within impermeable liner. Spill was all picked up.

Action Taken or Planned:

Line was locked out with valve and lock.

Wastes Disposal Location: All recovered wastes were disposed of into Leiseth SWD.

Agencies Involved:

Updates

Date: 8/7/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.