

Oil Field Environmental Incident Summary

Incident: 20150814233706 **Date/Time of Notice:** 08/14/2015 23:37

Responsible Party: RIM OPERATING, INC.

Well Operator: RIM OPERATING, INC.

Well Name: HOFFLUND 3

Field Name: HOFFLUND

Well File #: 1407

Date Incident: 8/13/2015 **Time Incident:** 17:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 95

Sec: 4

Qtr:

Location Description:

Submitted By: Troy Johnson

Received By:

Contact Person: Jason Rouse
5 INVERNESS DRIVE EAST
ENGLEWOOD, CO 80112

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels	26	Barrels		
Brine	70	Barrels	67	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Not Applicable

Areal Extent:

Potential Environmental Impacts:

Not Applicable

Action Taken or Planned:

The standing fluid was sucked up immediately after the incident. A cleaning crew was dispatched the following morning to wash and clean the area. The type of hose connection used it being replaced with new heavier grade fittings.

Wastes Disposal Location: The liquids will be processed at our Hofflund #2 tank battery. Solids will be hauled to Prairie Disposal.

Agencies Involved: NDIC - John Axtman
NDIC - John Rumppe

Updates

Date: 8/17/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.