

Oil Field Environmental Incident Summary

Incident: 20150815191300 **Date/Time of Notice:** 08/15/2015 19:13

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: CRYING TREE 8-1H

Field Name: LITTLE KNIFE

Well File #: 18718

Date Incident: 8/14/2015 **Time Incident:** 11:30

Facility ID Number:

County: DUNN

Twp: 147 **Rng:** 97 **Sec:** 8 **Qtr:**

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.3 Mile

Distance Nearest Water Well: 0.3 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 4 | Barrels | 3 | Barrels | 3 | barrels |

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/21/2015

Clean Up Concluded: 9/16/2015

Risk Evaluation:

The source of the release was secured upon discovery, and the release remained on location.

Areal Extent:

N/A - The release remained on location, inside of the tank berm.

Potential Environmental Impacts:

The release occurred above ground, and the released crude oil remained in the tank berm. A vacuum truck was dispatched to recover as much of the released crude oil as practicable.

Action Taken or Planned:

A vacuum truck was dispatched to recover as much of the released crude oil as practicable. Additional recovery work will be conducted inside of the tank berm in order to recover more of the released crude oil.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 8/17/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.