

Oil Field Environmental Incident Summary

Incident: 20150826173858 **Date/Time of Notice:** 08/26/2015 17:38

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: SCHROEDER 1-34H

Field Name: STONEVIEW

Well File #: 18259

Date Incident: 8/25/2015 **Time Incident:** 18:00

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 95

Sec: 34

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Lane Titus
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	1	Barrels	1	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

30 ft. by 50 ft.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Contaminated material was removed and replaced with clean fill.

Wastes Disposal Location: R360

Agencies Involved: Called John Rumpee @ 4:00 pm 8/26/2015

Updates

Date: 8/27/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.