

Oil Field Environmental Incident Summary

Incident: 20150901182814 **Date/Time of Notice:** 09/01/2015 18:28
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: DEKING 1-8-34MBH-ULW
Field Name: CAMEL BUTTE **Well File #:** 29051
Date Incident: 9/1/2015 **Time Incident:** 16:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 150 **Rng:** 96 **Sec:** 4 **Qtr:** LO T1
Location Description: Spill occurred offsite 150 yards SE from the Teton 21-3H well, which is located at 03 -Township 150 N Range 96 West.

Submitted By: Curtis Blaik **Received By:**
Contact Person: Curtis Blaik
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 450 Feet
Distance Nearest Water Well: 1000 Feet

Type of Incident: Pipeline Leak

Release Contained in Dike: No **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine 8 Barrels

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/18/2016 **Clean Up Concluded:** 10/20/2015

Risk Evaluation:

No immediate risk to human health or the environment.

Areal Extent:

Potential Environmental Impacts:

No immediate environmental impacts from the spill.

Action Taken or Planned:

Landowner will be notified and the spill cleaned up by excavating contaminated soil.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 9/2/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume: 8.00 barrels

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 9:30 a.m. Weather was sunny, 74 degrees. The area of impact is located in a field southwest of the pad. GPS N47.84580, W102.95782

You can see visible product on the surface of the soil. Area is about 30 feet by 10 feet on the surface of the stubble field.

Cleanup company is Steiner Oilfield Services; Conoco Philips will be overseeing the cleanup. Soil will be removed, the pipeline inspected and clean soil used to fill in the area impacted. Soil samples will be collected and sent for analysis. Sample results will be provided to NDDoH. Landowner stopped by and talked to NDDoH inspector and company personnel on site. He expressed concern about the issue and the need to have the area properly cleaned up. Additional followup will be needed for this site.

Date: 9/2/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Pipeline leak impacted surrounding area. Followup required.