

Oil Field Environmental Incident Summary

Incident: 20150903100033 **Date/Time of Notice:** 09/03/2015 10:00

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: BRADLEY ROBERT 1-12H

Field Name: DANEVILLE

Well File #: 29143

Date Incident: 9/2/2015 **Time Incident:** 08:00

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 102

Sec: 1

Qtr:

Location Description: LOT #3

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	1	Barrels		
Brine	8	Barrels	6	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Well shut in. Repairs made on equipment. Vacuum truck called for fluid cleanup. Surface contamination to be excavated.

Wastes Disposal Location: Fluid to the Legaard SWD, Solids to Secure 13 mile corner.

Agencies Involved:

Updates

Date: 9/3/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.