

Oil Field Environmental Incident Summary

Incident: 20150919091941 **Date/Time of Notice:** 09/19/2015 09:19
Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC
Well Name: BL-ODEGAARD- 156-95-2116H-9
Field Name: BEAVER LODGE **Well File #:** 30675
Date Incident: 9/18/2015 **Time Incident:** 01:00 **Facility ID Number:**
County: WILLIAMS **Twp:** 156 **Rng:** 95 **Sec:** 21 **Qtr:**

Location Description:

Submitted By: Jason Henry **Received By:**
Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 0.5 Mile
Distance Nearest Water Well: 0.5 Mile

Type of Incident: Other

Release Contained in Dike:	No	Reported to NRC:		No		
	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	0.7	Barrels				

Description of Other Released Contaminant:

Approximately 0.7 bbls of condensate was discharged through the flare stack during drilling operations.

Inspected: **Written Report Received:** 1/8/2016 **Clean Up Concluded:** 10/1/2015

Risk Evaluation:

The source of the release was secured immediately upon discovery. There were no injuries or evacuations as a result of this incident.

Areal Extent:

Approximately 750 square feet of impacted topsoil and vegetation, northeast side of well location.

Potential Environmental Impacts:

The release occurred above ground, and approximately 750 square feet of topsoil and vegetation were impacted by the release in the adjacent field to the northeast of the well location. There were no potential receptors observed in the vicinity of the release location.

Action Taken or Planned:

The impacted topsoil and vegetation will be excavated and transported off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 9/21/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Followup is required.

Date: 10/1/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 14:30. 66 degrees F, P. Cloudy, East wind 10-20 mph. Upon arrival contractors were in the process of removing equipment from the pad. Walked along the base (down-gradient) of the well pad and took photos. An area on the NE corner of the pad showed surface soil and vegetation removed from the side of the well pad and into the adjacent field approximately 25' wide by 60' long. There were no remaining indications of petroleum impacts to the soil or vegetation along the well pad or into the adjacent field. No further follow-up needed at this time.

Date: 11/25/2015 **Status:** No Further Action Requested

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received a cleanup report from the responsible party and its contractor. Sample results showed total petroleum hydrocarbons, electrical conductivity, sodium adsorption ratio, and chlorides to be within a reasonable range in comparison to background conditions. Report added to folder. No further followup needed at this time.

Date: 10/11/2016 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Brian O'Gorman sent a No Further Action letter dated October 11, 2016.