

# Oil Field Environmental Incident Summary

**Incident:** 20150921163450      **Date/Time of Notice:** 09/21/2015 16:34

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** EAGON 31-1SH

**Field Name:** CEDAR HILLS

**Well File #:** 16777

**Date Incident:** 9/21/2015      **Time Incident:** 08:00

**Facility ID Number:**

**County:** BOWMAN

**Twp:** 130

**Rng:** 106

**Sec:** 1

**Qtr:**

**Location Description:** Pasture to the NW of the Walter 11-1SH well site.

**Submitted By:** Patrick Skillestad

**Received By:**

**Contact Person:** Patrick Skillestad  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Barrels	3	Barrels	3	barrels
<b>Brine</b>	5	Barrels	5	Barrels	5	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 12/29/2016

**Clean Up Concluded:** 10/10/2015

**Risk Evaluation:**

None

**Areal Extent:**

30 ft wide x 60 ft long

**Potential Environmental Impacts:**

Topsoil in pasture.

**Action Taken or Planned:**

Flowline was shut in and sucked out. Flowline will be repaired. Visually contaminated soil will be removed.

**Wastes Disposal Location:** Little Missouri Special

**Agencies Involved:**

**Updates**

---

**Date:** 9/21/2015    **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted an area off location, therefore follow-up is necessary.

---

**Date:** 10/7/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

8/7/2015 at 16:26, on location. Pasture has been scraped to the NW of the Walter 11-1SH wellpad. No visible staining within scraped area; however, to the north and south of the scraped area some 2' x 2' spots are visible where staining is still present on the ground. Further scraping recommended to remove the remaining staining.

---

**Date:** 4/26/2016    **Status:** Inspection

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Visited the site. All stained areas had been remediated and had revegetated. No further action is warranted.

---

**Date:** 6/6/2016    **Status:** Correspondence

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Bill Suess sent a No Further Action letter dated June 6, 2016.