

Oil Field Environmental Incident Summary

Incident: 20151003092104 **Date/Time of Notice:** 10/03/2015 09:21

Responsible Party: MBI Energy Services

Well Operator: MARATHON OIL COMPANY

Well Name: ECKELBERG 14-23TFH

Field Name: BAILEY

Well File #: 21970

Date Incident: 10/3/2015 **Time Incident:** 01:00

Facility ID Number:

County: DUNN

Twp: 146

Rng: 94

Sec: 26

Qtr:

Location Description: Spill occurred in ditch along 98th ave near the intersection of 2nd St NW.

Submitted By: Chad Miller

Received By:

Contact Person: Chad Miller
PO Box 458
Belfield, ND 58622

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	60	Barrels				
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

The spill is contained in immediate vicinity and not migrating.

Potential Environmental Impacts:

Soil impacts

Action Taken or Planned:

Clean up crew has been contacted to complete cleanup

Wastes Disposal Location: Permitted Special Waste Landfill

Agencies Involved: Local Law Enforcement

Updates

Date: 10/5/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release was not contained; further followup required.

Date: 10/14/2015 **Status:** Inspection

Author: Crowder, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 10/14/2015, at 12:14 p.m. Release was to the ditch on the west side of 98th Ave, just north of 2nd St. An area approximately 100 x 20 ft has been scraped. Field conductivity readings in the scraped area are showing background levels. North of the scraped area approximately 30 yards, readings are in the 10-16 ms/cm range. Spoke to contact who had taken samples, and the results matched with my findings. Cleanup crew will be sent back out this week and will sample again once soil is removed. More followup required.

Date: 11/5/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Talked to MBI contact about sending the confirmation sample results.

Date: 11/6/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received information on the site regarding cleanup and sample results.

Date: 11/30/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 3:41 p.m. The weather was partly cloudy, 25°F, with wind from the northwest 0-5 mph. The cleanup area appears to have been extended to the north as indicated in the last inspection. The area has been regraded and seeded. Currently, the soil is frozen. No further followup is needed at this time.

Date: 12/14/2015 **Status:** No Further Action Requested

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Sent "No Further Action" letter to the company contact.