

Oil Field Environmental Incident Summary

Incident: 20151008161748 **Date/Time of Notice:** 10/08/2015 16:17
Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Name: ND STATE 158-95-21-28-2MBH
Field Name: MCGREGOR **Well File #:** 29310
Date Incident: 10/7/2015 **Time Incident:** 13:00 **Facility ID Number:**
County: WILLIAMS **Twp:** 158 **Rng:** 95 **Sec:** 16 **Qtr:**
Location Description: Spill was contained on well site.

Submitted By: Tappan Souther **Received By:**
Contact Person: Tappan Souther
1200 17TH STREET, SUITE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site **Reported to NRC:** No

| | Spilled | Units | Recovered | Units | Followup | Units |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 2 | Barrels | 2 | Barrels | | |

Brine

Other

Description of Other Released Contaminant:

Produce oil.

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

None

Areal Extent:

Spill contained on location.

Potential Environmental Impacts:

None

Action Taken or Planned:

Discussed with oil hauler about being diligent in the future.

Wastes Disposal Location: Local disposal.

Agencies Involved:

Updates

Date: 10/9/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on location according to the report. NDIC retains oversight.