

Oil Field Environmental Incident Summary

Incident: 20151011232726 **Date/Time of Notice:** 10/11/2015 23:27

Responsible Party: RON EVITT

Well Operator: JETTISON, INC.

Well Name: C.C.O.C. FEDERAL 1-24

Field Name: BEAR DEN

Well File #: 6368

Date Incident: 10/10/2015 **Time Incident:** 21:00

Facility ID Number:

County: MCKENZIE

Twp: 149

Rng: 96

Sec: 24

Qtr: SE SE

Location Description: Spill stayed on well site and lease road.

Submitted By: RON EVITT

Received By:

Contact Person: Ron Evitt
P.O. Box 562
Williston, ND 58802

General Land Use: Badlands Terrain

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels				

Brine

Other

Description of Other Released Contaminant:

only oil was released

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Less than 360 square feet estimated. The oil ran right down the road and stayed on the road.

Potential Environmental Impacts:

None.

Action Taken or Planned:

Will replace the entire line from the recycle pump to the treater. No oil was recovered, oil soaked into the ground, the entire oil spill stayed on the lease road.

The oil stained dirt was piled up and placed beside treater until the new line is installed.

Wastes Disposal Location: In a land fill. A little pile of oil stained dirt was placed near the treater. The old line will be dug up on and replaced with a new one October 12-15, 2015. The affected dirt will be disposed of after the new line is installed. This will be done since we will need to see if any dirt will need to be hauled out once the old line is dug up.

Agencies Involved:

Updates

Date: 10/12/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pipeline leak, remained on the facility site according to the report. NDIC retains oversight.