

# Oil Field Environmental Incident Summary

**Incident:** 20151022160218      **Date/Time of Notice:** 10/22/2015 16:02

**Responsible Party:** ONEOK Rockies Midstream

**Well Operator:** ONEOK ROCKIES MIDSTREAM

**Well Name:** Blu Buttes Compressor Station

**Field Name:** BLUE BUTTES

**Well File #:**

**Date Incident:** 10/20/2015      **Time Incident:** 09:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 95

**Sec:** 18

**Qtr:** SE SE

**Location Description:** 47.80390, -102.88290 ONEOK Compressor station

**Submitted By:** Byron Skaley

**Received By:**

**Contact Person:** Byron Skaley  
2700 Lincoln AVE. SE

Sidney, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1640 Feet

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	20	Gallons	20	Gallons		

**Description of Other Released Contaminant:**

Condensate Liquid

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Small fire was extinguished

**Areal Extent:**

10ft x 30ft

**Potential Environmental Impacts:**

No potential environmental impact

**Action Taken or Planned:**

the duration of the flare event was a very short, Small fire was extinguished

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 10/23/2015 **Status:** Reviewed - Follow-up Required

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Followup is required.

---

**Date:** 10/27/2015 **Status:** Inspection

**Author:** Washek, Sandi

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:** 20.00 gallons

**Updated Other Contaminant** Condensate liquid

**Notes:**

Arrived on site at 9:58 a.m. Weather was overcast and raining, 40 degrees F, light wind. The location where the condensate fire occurred was GPS N47.80561, W102.88326. The fire was right under the flare on the west side of the fence. The soil does not appear stained. The fire burned the vegetation along the road accessing the back portion of the company's lot. The condensate/fire did not appear to reach water or the main ditch of the highway. No additional followup needed.