

Oil Field Environmental Incident Summary

Incident: 20151028110300 **Date/Time of Notice:** 10/28/2015 11:03

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P JORGENSON 154-98-5-14-23-16H

Field Name: TRUAX

Well File #: 21817

Date Incident: 10/27/2015 **Time Incident:** 22:30

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 14

Qtr: NW SW

Location Description:

Submitted By: Corissa Zimmer

Received By:

Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.8 Mile

Distance Nearest Water Well: 0.8 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels			0.8	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 11/2/2015

Risk Evaluation:

None noted.

Areal Extent:

The mist went north of the pad and covered about 60' by 100' of an adjacent field.

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

The valve was opened to stop the treater upset. Whiting will clean the spill soon, most likely by mowing and hydrovac truck usage. Whiting is investigating the cause of the spill. Whiting will increase awareness about valve shutting protocol in the treater shed for both employees and contractors. Whiting will also increase security and awareness of potential vandalism to prevent a reoccurrence.

Wastes Disposal Location: Wastes will be disposed of at an approved facility.

Agencies Involved:

Updates

Date: 10/28/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained. Followup required.

Date: 10/29/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 10/29/2015.

Minimal impacts to areas off of location. The responsible party is planning on cutting the impacted vegetation and removing it.

No followup is necessary.