

Oil Field Environmental Incident Summary

Incident: 20151030165511 **Date/Time of Notice:** 10/30/2015 16:55

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P WOOD 154-98-14-22-15-2H3

Field Name: TRUAX

Well File #: 29810

Date Incident: 10/30/2015 **Time Incident:** 15:20

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 22

Qtr:

Location Description:

Submitted By: Corissa Zimmer

Received By:

Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons			8	gallons
Brine	7	Barrels			6.5	gallons

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/8/2016

Clean Up Concluded: 10/30/2015

Risk Evaluation:

None noted.

Areal Extent:

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

Whiting will increase awareness to maintenance personnel regarding accidentally compromising hammer unions during work on lines that go to LACTS. The hydrovac is currently on the way to suck up any standing fluid (as of 4:40 PM on 10/30/15) and any impacted soil will be removed following a one-call.

Wastes Disposal Location: Any sucked up fluid or impacted soil will be disposed of an approved facility.

Agencies Involved:

Updates

Date: 11/2/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.