

Oil Field Environmental Incident Summary

Incident: 20151102160404 **Date/Time of Notice:** 11/02/2015 16:04

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: RS-R HARSTAD-157-90- 2029H-1

Field Name: CLEAR WATER

Well File #: 18046

Date Incident: 11/2/2015 **Time Incident:** 07:30

Facility ID Number:

County: MOUNTRAIL

Twp: 157 **Rng:** 90 **Sec:** 20 **Qtr:**

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	1.2	Barrels				

Description of Other Released Contaminant:

Emulsion

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

12' by 51' (Onsite) 25' by 87.5' (Offsite)

Potential Environmental Impacts:

There are potential impacts to an estimated 25' by 87.5' area offsite.

Action Taken or Planned:

Arrangements have been made to have the impacted areas cleaned up.

Wastes Disposal Location: The recovered wastes will be taken to an approved waste disposal facility.

Agencies Involved:

Updates

Date: 11/2/2015 **Status:** Reviewed - Follow-up Required **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident report, release impacted area off location. Followup is required.

Date: 12/15/2015 **Status:** Inspection **Author:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 11:00. 19 degrees F, foggy, NW wind 0-5 mph. 1-2 inches of fresh snowfall covering ground surface. Observed the site and took photos. It appeared that the release occurred east of the heater/treater due to the lack of vegetation holding snow, in comparison to the surrounding landscape. Estimate of the area was 75' by 150' on the eastern side slope (approximate 20% slope) of the well pad.

Follow up with company to review soil lab samples and/or with spring/summer 2016 visual observations of the area.