

# Oil Field Environmental Incident Summary

**Incident:** 20151124141216      **Date/Time of Notice:** 11/24/2015 14:12

**Responsible Party:** Oneok

**Well Operator:** STATOIL OIL & GAS LP

**Well Name:** M. ELLIS 4-9 #1-H

**Field Name:** WILLISTON

**Well File #:** 22132

**Date Incident:** 11/23/2015      **Time Incident:** 15:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 100

**Sec:** 4

**Qtr:** LO T2

**Location Description:** 54th Street NW & 53rd Street NW

**Submitted By:** Richard Wright

**Received By:**

**Contact Person:** Kimberly Rudningen  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 500  
AUSTIN, TX 78730

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	5	Barrels	5	Barrels		

**Description of Other Released Contaminant:**

Condensate

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Elevated LELs, top soil contamination

**Areal Extent:**

Spill was contained

**Potential Environmental Impacts:**

Potentially high salt concentrations mixed with hydrocarbons

**Action Taken or Planned:**

Spill was contained within a 40'X40' area of the excavation where line was struck  
SK&S vacuumed up condensate and soil soon after the spill occurred and will return morning of 11/24/15 to begin removing up 6 inches of contaminated top soil.

**Wastes Disposal Location:** Secure Energy 13 Mile Corner

**Agencies Involved:**

**Updates**

---

**Date:** 11/25/2015 **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release impacted an area off location. Further followup is required.

---

**Date:** 12/1/2015 **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site 11:37 p.m. The weather was sunny, 18°F, with wind from the west 0-5 mph. The pipeline strike was just off the southeastern corner of the pad in the stubble field. Currently, a construction company is working on the pad in this corner. The pipeline has been repaired, and the area has been covered. Construction company personnel indicated that the impacted soil has been hauled away. No further followup needed. I requested confirmation sample results. 48.19658, -103.54391

---

**Date:** 12/3/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Requested any documentation the company has about the site.

---

**Date:** 12/4/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

NDDoH will receive sample results when company contact receives them.

---

**Date:** 12/14/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received sample results and information about how the spill was cleaned up.

---

**Date:** 12/15/2015 **Status:** No Further Action Requested

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Sent "No Further Action" letter to company contact.