

Oil Field Environmental Incident Summary

Incident: 20151205110438 **Date/Time of Notice:** 12/05/2015 11:04

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: CHSU 13-36NH 26

Field Name: CEDAR HILLS

Well File #: 15330

Date Incident: 12/4/2015 **Time Incident:** 16:00

Facility ID Number:

County: BOWMAN

Twp: 132 **Rng:** 106 **Sec:** 36 **Qtr:**

Location Description: Majority of spill remained on location. Approximately 33 bbls left location in a small flow to the S and N of location.

Submitted By: Josh Cuppy

Received By:

Contact Person: Josh Cuppy
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	213	Barrels				

Description of Other Released Contaminant:

Harr source water.

Inspected:

Written Report Received: 7/27/2016

Clean Up Concluded: 6/14/2016

Risk Evaluation:

None

Areal Extent:

Majority contained on location. Appro 33 bbls left location to N and S of location.

Potential Environmental Impacts:

None

Action Taken or Planned:

Recovery of water is not possible as soaked into ground quickly. Impacted area off location is being flushed and recovered. Location will be back dragged.

Wastes Disposal Location: NA

Agencies Involved: BLM

Updates

Date: 12/7/2015 **Status:** Reviewed - Follow-up Required

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spoke with Josh Cuppy at Denbury. Denbury has sample data of the Harr source water and will forward to NDDoH for review.

Date: 1/25/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received sample data from Harr Source Water. Due to elevated chloride levels in the source water (1,200 mg/L), the site should be inspected in the spring of 2016 to assure proper revegetation has occurred.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

6/14/2016 at 13:17, on location. Area to north of wellpad has been reseeded. Unclear whether it was reseeded due to incident or for the recently installed pipeline that leads to the wellhead on site. Regardless, vegetation is regrowing, and there are no noticeable barren patches on the north side. On the south side, there is continuous vegetation along the edge of the wellpad's berm. Some spots further away (~50-100 ft further south) have sparser vegetation; however, no dead vegetation is visible in these areas so they appear to be unrelated to the incident. No further follow-up required at this time.