

Oil Field Environmental Incident Summary

Incident: 20151217115302 **Date/Time of Notice:** 12/17/2015 11:53

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: SFTU 2-35

Field Name: FRYBURG

Well File #: 13205

Date Incident: 12/16/2015 **Time Incident:** 12:25

Facility ID Number:

County: BILLINGS

Twp: 139

Rng: 101

Sec: 35

Qtr:

Location Description: On location

Submitted By: Josh Cuppy

Received By:

Contact Person: Brian Ehrmantraut
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 3 Mile

Distance Nearest Water Well: 3 Mile

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	7	Barrels	7	Barrels	1	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/4/2016

Clean Up Concluded: 12/21/2015

Risk Evaluation:

None

Areal Extent:

Contained in dike

Potential Environmental Impacts:

None

Action Taken or Planned:

The well was shut in and the treater isolated and drained. A vac truck was dispatched to suck up the standing fluid. 6 of the 7 bbls were sucked up and the rest soaked into the ground. The contaminated soil will be excavated and hauled to an approved landfill.

Wastes Disposal Location: R360

Agencies Involved: BLM
Forest Service

Updates

Date: 12/17/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.