

Oil Field Environmental Incident Summary

Incident: 20151218090532 **Date/Time of Notice:** 12/18/2015 09:05

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: L. HOIBY 159-94-30D-19-4H

Field Name: NORTH TIOGA

Well File #: 27247

Date Incident: 12/16/2015 **Time Incident:** 23:30

Facility ID Number:

County: BURKE

Twp: 159 **Rng:** 94 **Sec:** 31 **Qtr:**

Location Description: Spill occurred on well site and adjacent wheat stubble and tree row.

Submitted By: Derek Enderud

Received By:

Contact Person: Derek Enderud
PO BOX 935
BISMARCK, ND 58502

General Land Use: Other - Described Above

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	50	Barrels			50	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/6/2016

Clean Up Concluded: 12/22/2015

Risk Evaluation:

None.

Areal Extent:

Impacted area was approximately 300 yds x 400 yds.

Potential Environmental Impacts:

None. Mist off location stayed on snow surface.

Action Taken or Planned:

Well was shut down when discovered. Vac truck and hot oil truck started cleaning up location, removed fluids and contaminated snow/well surfacing. Tree row adjacent to well pad was washed down with freshwater and fluid removed. The mist stayed on top of the snow in the adjacent field. A blade was brought in to windrow the contaminated snow; the snow is being loaded into trucks and taken to PDI disposal. The remaining contaminated snow will be hauled off tomorrow. Some fine mist reached surface owner's shop approximately 400 yds to the east. Surface owner was notified and aware of all activity.

There is very little chance the oil touched the frozen ground, it all appeared to stay on surface. However, soil samples will be taken in the cropland in the spring to verify there were no impacts. The impacted trees will also be monitored during the growing season for any lasting effects.

Wastes Disposal Location: PDI - TIOGA

Agencies Involved:

Updates

Date: 12/18/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, there was a release of oil that misted off of the well pad. Further followup required.

Date: 12/20/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12:18, 12/20/2015.

Area impacted to east of location. Trees, snow and soil impacted. Impacted snow has been scraped up with only a small amount of impacted snow between trees in tree row. More followup with company is necessary to determine what actions are to be taken with the impacted trees and the snow in between the impacted trees.

More followup is necessary.