

Oil Field Environmental Incident Summary

Incident: 20160115152548 **Date/Time of Notice:** 01/15/2016 15:25
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: BLEGEN 34-24TFH
Field Name: BLUE BUTTES **Well File #:** 24119
Date Incident: 1/15/2016 **Time Incident:** 14:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 151 **Rng:** 96 **Sec:** 24 **Qtr:** SW SW
Location Description: Immediately adjacent to the southern edge of the well pad.

Submitted By: Lewis Schoenberger **Received By:**
Contact Person: Lewis Schoenberger
600 N. DAIRY ASHFORD
HOUSTON, TX 77079

General Land Use: Cultivated **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 0.3 Mile
Distance Nearest Water Well: 0.3 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/18/2016 **Clean Up Concluded:** 1/26/2016

Risk Evaluation:
None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

The well has been shut in. A vacuum truck will be used to collect puddled liquid. Oil impacted snow off of the pad will be collected for appropriate oil recovery. Oil impacted gravel on the pad will be collected for appropriate disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/15/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a packing leak, was not contained to the facility. More followup needed.

Date: 1/20/2016 **Status:** Inspection

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site 2:30 p.m. 16 degrees, 5-10 mph NW. Majority of spill stayed close to the wellhead. Spray did leave the pad to the SW. Area impacted off site is approximately 50 yds X 75 yds. Area has been scraped up and stockpiled on site. Scraped area still contained remnants of oil in small straight lines and small blotches - yellow streaks. I also noticed that contamination did extend beyond the scraped area and reached the pinnacle of the ditch. Contamination was communicated to the cleanup crew, and I was told they would take care of it with the hydro-vac. More follow-up is needed to check on disposal of material, vegetative growth (spring and seeding). Cleanup contractor was "TITAN". Contact on site was nicknamed "Nip".