

Oil Field Environmental Incident Summary

Incident: 20160120135145 **Date/Time of Notice:** 01/20/2016 13:51

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BL-DOMY-156-95- 2932H-1

Field Name: BEAVER LODGE

Well File #: 16944

Date Incident: 1/20/2016 **Time Incident:** 07:15

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 95

Sec: 29

Qtr: NW NE

Location Description:

Submitted By: Alberto Yates

Received By:

Contact Person: Troy Brunsell
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1000 Feet

Distance Nearest Water Well: 1000 Feet

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine					0	barrels
Other	2.5	Barrels			2.5	barrels

Description of Other Released Contaminant:

Emulsion spill from a failed radigan on the stuffing box.

Inspected:

Written Report Received: 1/28/2016

Clean Up Concluded: 1/26/2016

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

The total area was 448'x70', 254 ft x 70 area onsite, and 194 ft x 70 ft area offsite to the west.

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time.

Action Taken or Planned:

Well was shut down and depressured to stop it from producing. Arrangements were made for the impacted material to be cleaned up and disposed of. The recovered waste will be taken to an approved waste disposal facility.

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:

Updates

Date: 1/20/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, impacted soil off the well pad. Further followup needed.

Date: 1/21/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 1/21/2015.

Impacted snow scraped up and stacked on location. More followup is necessary in spring due to recent snows obscuring impacted area.

More followup is necessary.

Date: 3/7/2016 **Status:** Inspection

Author: Torgerson, Brad

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Viewed site on March 1, 2016. Area outside the deadmen (buried rig anchors), about 50 yards SW of the wellhead, appeared to have been excavated. No oil staining observed SW of well head. Recommend checking vegetation growth during the growing season.

Date: 7/12/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 7/12/2016, at 10:25 a.m. Walked the perimeter of well pad. Vegetation is green and growing with no signs of distress. No further follow-up required.