

# Oil Field Environmental Incident Summary

**Incident:** 20160201101811      **Date/Time of Notice:** 02/01/2016 10:18

**Responsible Party:** TAQA NORTH USA, INC.

**Well Operator:** TAQA NORTH USA, INC.

**Well Name:** Grenora CTB

**Field Name:** GRENORA

**Well File #:**

**Date Incident:** 1/31/2016      **Time Incident:** 12:49      **Facility ID Number:** 205770-01

**County:** DIVIDE      **Twp:** 159      **Rng:** 103      **Sec:** 29      **Qtr:** SE SW

**Location Description:**

**Submitted By:** Casey Elm

**Received By:**

**Contact Person:** Casey Elm  
7400 E Caley Ave Ste 200  
WAS:PRIMEWEST PETROLEUM, INC  
Centennial, CO 80111

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** Yes

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	50	Barrels	49	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

oil inside of dikes contaminating soil at facility

**Areal Extent:**

**Potential Environmental Impacts:**

contaminate soil

**Action Taken or Planned:**

Sucked up fluid? all recycle lines shall be shut at tank to keep from flowing back when this occurs

**Wastes Disposal Location:** Proper disposal

**Agencies Involved:**

**Updates**

---

**Date:** 2/1/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release was contained within the well pad perimeter. NDIC has oversight.