

Oil Field Environmental Incident Summary

Incident: 20160204150211 **Date/Time of Notice:** 02/04/2016 15:02

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: WALTER 11-1SH

Field Name: CEDAR HILLS

Well File #: 17131

Date Incident: 2/4/2016 **Time Incident:** 08:00

Facility ID Number:

County: BOWMAN

Twp: 130

Rng: 106

Sec: 1

Qtr:

Location Description: Pasture adjacent to well site.

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	gallons
Brine	1	Barrels	1	Barrels	1	gallons

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/12/2016

Clean Up Concluded: 2/5/2016

Risk Evaluation:

None

Areal Extent:

60 ft x 60 ft

Potential Environmental Impacts:

Majority of fluid stayed on location around wellhead, a small area off location was very lightly misted. Misted fluids off location stayed on top of snow.

Action Taken or Planned:

Misted snow was scraped up, contaminated material and fluids around wellhead were vacced up.

Wastes Disposal Location: Petrocomp

Agencies Involved:

Updates

Date: 2/4/2016 **Status:** Reviewed - Follow-up Required **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release did not stay on well pad. Further followup necessary.

Date: 2/11/2016 **Status:** Correspondence **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Contacted Continental Resources, Inc. for correct well location:
N 46.1054800
W 103.9013900

Date: 3/8/2016 **Status:** Inspection

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 10:15 a.m. 39 degrees F, wind 5-10 mph. No well jack present. Wellhead is inside cattleguard fencing. Vegetative growth around site appears normal. Walked perimeter of site and took pictures. No visual contamination was present on or off site of this location. However, further inspection of area sites found that this well location is linked to a nearby pipeline repair. Two other incidents also fit this description. They are as follows:

Incident Number 20160204150211 - Walter 31-2SH

Incident Number 20160301095727 - Eagon 31-1SH - closest to actual spill location

For record-keeping purposes. I will update these incidents as recorded in my notes and will check with Spill Response Program manager to determine which sites he would like to close.

Date: 4/26/2016 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site. All vegetation in the area looked good. The disturbed area NW of the well pad is due to pipeline construction and not the release. No further action is warranted.

Date: 6/6/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.