

Oil Field Environmental Incident Summary

Incident: 20160210190028 **Date/Time of Notice:** 02/10/2016 19:00

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: HOLSTEIN FEDERAL 2-25H

Field Name: ELM TREE

Well File #: 27564

Date Incident: 2/10/2016 **Time Incident:** 07:30

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 94

Sec: 25

Qtr:

Location Description: well location and adjacent crop stubble field

Submitted By: Todd Senescall

Received By:

Contact Person: Travis Siminiowniw
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	8	Barrels	7	Barrels	8	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/5/2016

Clean Up Concluded: 3/23/2016

Risk Evaluation:

fire

Areal Extent:

approximately 200 square feet of the stubble field was impacted.

Potential Environmental Impacts:

topsoil

Action Taken or Planned:

Valve was closed. Standing fluid was sucked up. Contaminated soil, ice and snow are being recovered.

Wastes Disposal Location: Secure Energy
recovered ice to the flare pit.

Agencies Involved: NDDH

Updates

Date: 2/11/2016 **Status:** Reviewed - Follow-up Required **Author:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, was not contained according to the report. More followup needed.

Date: 2/18/2016 **Status:** Inspection **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I talked to a company rep, and he was able to direct me to the site. He also indicated that the area had been cleaned up. I arrived at the site 12:36 p.m. The weather was cloudy and 32°F, with wind from the southeast 5-10 mph. The area had recent snow, and I could see dirt pushed up along the edges of the cleaned-up area. The spill occurred just off the edge of the pad near the building in a flat stubble field. More follow-up needed. 48.04881, - 102.71919