

Oil Field Environmental Incident Summary

Incident: 20160301095727 **Date/Time of Notice:** 03/01/2016 09:57

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: EAGON 31-1SH

Field Name: CEDAR HILLS

Well File #: 16777

Date Incident: 2/29/2016 **Time Incident:** 09:00

Facility ID Number:

County: BOWMAN

Twp: 130

Rng: 106

Sec: 1

Qtr:

Location Description: Pasture adjacent to flowline ROW.

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels	4	Barrels	4	barrels
Brine	6	Barrels	6	Barrels	6	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/12/2016

Clean Up Concluded: 3/3/2016

Risk Evaluation:

None

Areal Extent:

4 ft x 400 ft

Potential Environmental Impacts:

Topsoil in pasture.

Action Taken or Planned:

Flowline was shut in. Standing fluid was sucked up and repairs are underway. Contaminated fluid will be removed and disposed of.

Wastes Disposal Location: Fluids to Petrocomp and solids to Little Missouri Special.

Agencies Involved:

Updates

Date: 3/1/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained to the well pad, and it impacted pastureland. More follow-up needed.

Date: 3/8/2016 **Status:** Inspection

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on-site 10:40 a.m. Walked entire perimeter of site. Did not notice any excavation immediately off site. There is a location to the northwest where heavy machinery is located. It was discovered that multiple incidents are tied to a single location; however, they were reported as different sites relative to the location and which were in the vicinity.

The two other incidents are as follows:

Incident Number 20160223101909

Incident Number 20160204150211

Date: 4/26/2016 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site. All vegetation in the area looked good. The disturbed area NW of the well pad is due to pipeline construction and not the release. No further action is warranted.

Date: 6/6/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.