

Oil Field Environmental Incident Summary

Incident: 20160302162439 **Date/Time of Notice:** 03/02/2016 16:24

Responsible Party: Lime Rock Resources

Well Operator: OXY USA INC.

Well Name: NOVASIO STATE 1-16-21H-142-95

Field Name: MURPHY CREEK

Well File #: 20024

Date Incident: 3/2/2016 **Time Incident:** 11:30

Facility ID Number:

County: DUNN

Twp: 142

Rng: 95

Sec: 16

Qtr:

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
PO BOX 2000
DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels	3	barrels
Brine	22	Barrels	22	Barrels	22	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/9/2016

Clean Up Concluded: 3/4/2016

Risk Evaluation:

Contaminated surface material

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material

Action Taken or Planned:

The well was shut in, the rubbers were changed and a vac truck was immediately dispatched to recover all standing fluids. SM Fencing has been dispatched and will assist in further remediation.

Wastes Disposal Location: Chimney Butte

Agencies Involved:

Updates

Date: 3/4/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was contained to the well pad. NDIC has oversight.