

# Oil Field Environmental Incident Summary

**Incident:** 20160724150400      **Date/Time of Notice:** 07/24/2016 15:04

**Responsible Party:** Thomas Dockstader

**Well Operator:** R360 WILLISTON BASIN, LLC

**Well Name:** Smoky Butte Environmental LLC. Landfill

**Field Name:**

**Well File #:**

**Date Incident:** 7/23/2016      **Time Incident:** 06:00

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 161      **Rng:** 100      **Sec:** 14      **Qtr:** NE

**Location Description:** Smoky Butte Environmental LLC Landfill  
13310 94th Street NW, Fortuna ND 58844

**Submitted By:** Adrian Trim

**Received By:**

**Contact Person:** Adrian Trim  
102C10 52 St NW  
Tioga, ND 58852

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 3 Mile

**Distance Nearest Water Well:** 3 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

No Release Of Materials-FIRE

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No immediate risk. Fire was smothered by drill cuttings.

**Areal Extent:**

Contained. approximately 20' by 40' of landfill HDPE liner was damaged.

**Potential Environmental Impacts:**

Clay soil liner below burnt HDPE is in contact with drill cuttings from landfill. No groundwater potential impacts. No surface water potential impacts.

**Action Taken or Planned:**

Smothered fire with dirt. Will re-line damaged area with correct materials and sample underlying clay for impacts.

**Wastes Disposal Location:** In landfill.

**Agencies Involved:** Local Fire Department Local Law Enforcement

**Updates**

---

**Date:** 7/25/2016    **Status:** Reviewed - Assigned to NDDoH Division    **Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, this incident occurred at the R360 landfill. NDDoH Division of Waste Management retains oversight.